



Before running cable, step off from control center to splitter under stage. Hopefully, can use 75' SDI cable. If not, 100' is available.

Two new 40' HDMI cables from splitter under stage to screens.

Checklist:

- Switcher
- (2) Cameras
- Monitor
- Monitor arm
- (1) HDMI to SDI converter
- SDI to HDMI converter
- (3) Power strips

- White table
- Wire staples
- Hammer
- Rags
- Beer mugs
- Ladder
- Allen wrenches
- Snips

- Zip ties